

Santa Fe Springs Department of Fire-Rescue

Environmental F tection Division • Certified Unific 'rogram Agency 11300 Greenstone Ave _ Santa Fe Springs • CA 90670 (562) 944-97.3 FAX (562) 941-1817

INSPECTION REPORT & NOTICE OF VIOLATION

Business name Filection, Olyme & Grinding

Page 1 of

Address

Santa Fe Springs, CA 90670

The following items, if applicable, have been inspected. This document constitutes a Summary of Violations and Notice to Comply if the violation (V) column is checked. Reference: Titles 19, 22, and 23 of the California Code of Regulations (CCR), Chapters 6.5, 6.67, 6.95 of the Health and Safety Code (HSC), The California

tion	Inspector(s) Educatal Mun				Inspection date			
Inspection consent given by Wile Van					Contact phone number (っぱつ) 946-66元			
HAZARDOUS WASTE GENERATOR				HAZARDOUS WASTE GENERATOR				
V	SUBJECT	REFERENCE		٧	SUBJECT	REFERENCE		
Haza	irdous waste generator permit	City Code 97,400	26	1	Contingency plan for LQG	CCR 66265.51		
	ID number/CA Waste ID number	CCR 66262.12 (a)	27		Emergency preparedness/prevention LQG	CCR 66265.30		
	irdous waste determination	CCR 66262 11	28	III.	SB14 requirements for LQGs	CCR 67100.3		
Prop	er disposal of hazardous waste	HSC 25189.5 (a)	29		Excluded recyclable material management	HSC 25143 29		
Reck	dess management of hazardous waste	HSC 25189.6 (a),	30		Proper management of Universal Waste	CCR 66273.13		
M Haza	ordous waste labeling	CCR 66262.34 (f)			HAZARDOUS MATERIALS BI	USINESS PLAN		
Haz	Waste/Satellite accumulation time	CCR 66262.34 (a-d)/(e)	31		HMBP established, implemented, filed	HSC 25503.5		
Retr	ngrade/speculative accumulation	CCR 66261.2 (d)	32		Minimum standards for business plans	CCR 2729		
Haza	ordous waste containers closed	CCR 66265,173 (a)			INDUSTRIAL WA	STE		
Cont	ainers mislabeled, deteriorated, etc.	CCR 56262.2 (f)	33		Generating industrial waste w/o a permit	City Code, Ch. 97		
Cont	tainer storage inspection - weekly	CCR 66265.174			CALIFORNIA FIRE	CODE		
Man	agement of empty containers	CCR 66261.7	34		Maximum allowable hazardous materials	CFC 2703.1.1		
	foil management	HSC 25250.4	35	tt	Separation of incompatible materials	CFC 2703.9.8		
	d oil filter management	CCR 66266.130	36		Secure compressed gas cylinders	CFC 303		
	aminated textile management	HSC 25144.6	37		Fire protection system maintenance	CFC 901.6.1		
	c inspection - daily	CCR 66265.195	38	+ +	Service and tag kitchen hood system	CFC 904.11 6 4		
	coperating requirements	CCR 66265.194	39	1	Clearance from electrical control panels	CFC 605.3		
	ifest general requirements	CCR 66262.20-23	40	++	Exits free from obstructions	CFC 1028		
	ifest completed	CCR 66262.23 (a)	₩.;•	1	STORM WATE			
	solidated manifest requirements	HSC 25160.2	41	† †	Storm water permit required (GIASP)	City Code, Ch. 52		
	ifest copies retained for 3 years	CCR 66262.40 (a)	42	1-+	Failure to implement BMPs	City Code, Ch. 52		
	nial report for RCRA LQG	CCR 66262.40 (b)	1		CALARP			
	erdous waste analysis retained 3 years	CCR 66252.40 (c)	43		CalARP required	19 CCR 2745.1 (b)(3		
	onnel Training Plan for LQGs	CCR 66265.16	-11	 	OTHER VIOLATI			
	onnel training for generators of waste	CCR 66262.34 (d), 40CFR	44 -	1	Other violation(s)			
pection Cat	egory: Single Program Com		ulti-Med	dia		of Employees: \\		
	slup that recycl	was inspect	ulti-Med	dia Fü	Number of school close who the			
tes: O	slup that recycl		ulti-Med	sol	Number of scripty is a hard clustering back into the script and loss	······································		
No hazar Notice to Return a ention: The rid result in r	rdous waste violation(s) observed tracked "Certificate of Completen(s) checked is (are) in violation. All transpection fees, permit revocation, and	erved on date of insport the corrected by liance"	ection d. A reminal per	Solution Sol	Number of scripty is a hard clustering back into the script and loss	iance. Non-compliance		



Cir of Santa Fe Springs Fire Departmer

Environment rotection Division m Certified Unified Progr. m Agency
11300 Greenstone Ave Santa Fe Springs CA 90670 (562) 944-9713 FAX (562) 941-1817

INSPECTION REPORT & NOTICE OF VIOLATION



Page 2_ of 2_

	NESS Electronic Chrome and Grinding	SITE ADDRESS 9132 Dice Road, Santa I	e Springs, CA 90670					
	TACT Mike Reed							
INSPI	ECTED BY Richard Kallman	DATE INSPECTED 10/11/11						
and	ference: Titles 19 and 22 of the California Code of . d Safety Code (HSC), and Chapter 97 of the City Co	de.						
6.	Electronic Chrome and Grinding violated 22CCR66262,34(f) by not properly labeling hazardous waste containers. The grinding sludge container's label was illegible and had no accumulation start date. Electronic Chrome and Grinding must ensure that all waste containers are properly and completely labeled.							
	Electronic Chrome and Grinding violated 22CCR66262.34 by storing hazardous waste for longer than allowed. Two totes of chrome waste had an accumulation start date of May 23, 2011 and a tote of waste oil had an accumulation start date of March 2011. Electronic Chrome and grinding must properly dispose of this material and ensure that wastes are not stored longer than 90 days unless satellite accumulation requirements are met.							
11.	Electronic Chrome and Grinding violated 22CCR66 sheets showed no problems on the site, but waste w there was waste on top of the waste oil tote. Electrodeficiencies and correct any deficiencies that are fo	as stored for longer than allowed, containers vonic Chrome and Grinding must conduct accu	vere not properly labeled,					
28.	Electronic Chrome and Grinding violated 22CCR67 review. Electronic Chrome and Grinding must sho submitted to the DTSC. If the report has not been of DTSC.	7100.3 by not having their SB14 summary pro we evidence that the summary progress report completed, the facility must complete the report	was completed and rt and submit it to the					
44A.	Electronic Chrome and Grinding violated 22CCR6 in the middle of the floor had an accumulation of a shop owner, it is apparent that the pit had not been management, wastes from floors must be removed the shift. Electronic Chrome and Grinding must en	pproximately 2 inches of chrome laden waste, pumped in a few days. Per the DTSC Guidanin a timely manner, and at the very least should be a second or the property of the proximal and a second or the proximal architecture.	From discussions with the ce document on wet floor d be removed by the end of					
44B.	Electronic Chrome and Grinding violated 22CCR66 facility added a new filter press without having it concertified. Additionally, the last tank certification we recertification. Electronic Chrome and Grinding metals.	ertified and modified their secondary containn as completed in July of 2006 and the tanks are	nent without having it now overdue for					
			AAN A A					
~ ~	Correct Violations by November 13, 2011 (exc	cept item 44B which must be completed by	January 13, 2012)					
	Mile Roed Signature	Mike Reed	\\-\3-\\ Date					